

## GREISINGER CLIMATE MEASURING - HYGROMETER /THERMOMETER/BAROMETER

GFTB 200

GFTB-200

Hygrometer / thermometer / barometer

- Designed for measuring air pressure, air humidity and temperature within seconds.
- Electrical isolated interface converter, directly connectable to PC.
- Scope of supply: Device, battery, calibration protocol, manual
- High precision sensors provide remarkable accuracy



### PRODUCT DESCRIPTION

### TECHNICAL DATA

<b>Dimensions</b>	106 x 67 x 30 mm
<b>Display</b>	4½ digit LCD, 11mm high
<b>Housing material</b>	ABS plastic
<b>Measuring Application</b>	Temperature, Air Humidity, Air Pressure
<b>Measuring Range: Air Humidity</b>	0.0 ... 100.0 %RH
<b>Measuring Range: Air Pressure</b>	10.0 ... 1100.0 mbar
<b>Measuring Range: Temperature</b>	-25 ... 70°C
<b>Operating temperature</b>	-25 ... 70°C
<b>Power</b>	9 V Battery
<b>Resolution</b>	0.1%RH, 0.1°C or 0.1mbar
<b>Type</b>	Humidity Measuring
<b>Weight</b>	130 g

